HA-1620 WHITE FRAME BUNGALOW 3229 Churchville Road Churchville vicinity Private

Early 20th century

The white frame bungalow is a fair example of an early 20th century building form which became common in all parts of the U.S. Although altered, it retains the general outline of the bungalow form.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME				
HISTORIC				
AND/OR COMMON				
	hite Frame Bungalo	W		
2 LOCATION	V			
STREET & NUMBER				
3229 Ch	urchville Rd.			
CITY, TOWN	CONGRESSIONAL			ICT
Churchy STATE	11e X VICINITY OF COUNTY		······································	
Marylan			Harford	
3 CLASSIFIC	CATION			
CATEGORY	OWNERSHIP STATUS		PRESENT USE	
DISTRICT	PUBLIC	_XOCCUPIED	AGRICULTURE	MUSEUM
_XBUILDING(S)	XPRIVATE	_UNOCCUPIED	COMMERCIAL	PARK
STRUCTURE	ВОТН	WORK IN PROGRESS	EDUCATIONAL	XPRIVATE RESIDENCE
SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	RELIGIOUS
OBJECT	IN PROCESS	YES: RESTRICTED	GOVERNMENT	SCIENTIFIC
	BEING CONSIDERED	YES: UNRESTRICTED	iNDUSTRIAL	TRANSPORTATION
			MILITARY	OTHER
4 OWNER O	FPROPERTY			
NAME			Telephone #:	
STREET & NUMBER			TOTOPHONE #:	
CITY, TDWN			STATE . Z	ip code
		VICINITY OF		ip code
5 LOCATION	N OF LEGAL DESCR	IPTION	Liber #:	
COURTHOUSE.			Folio #:	
REGISTRY OF DEEDS,	ETC. Harford County	Court House	LOTIO #:	
STREET & NUMBER		court nouse		
	40 So. Main St			
CITY, TOWN	D-1 -1'		STATE	
A DEDDE GEN	REPRESENTATION IN EXISTING SURVEYS		MD 510.	14
6 REPRESEN	TATION IN EXIST	NG SURVEYS		
TITLE				
DATE				
DEBOGITORY		FEDERAL _	_STATECOUNTYLOCAL	
DEPOSITORY FOR SURVEY RECORDS				
CITY, TOWN			STATE	
				
				



NA-1650

CONDITION

CHECK ONE

CHECK ONE

_EXCELLENT
XGOOD
_FAIR

__DETERIORATED
__RUINS
__UNEXPOSED

_unaltered

X_ORIGINAL SITE
__MOVED DATE_____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The White Frame Bungalow at 3229 Churchville Rd. (MD 22) is a 1-1/2 story early 20th century house with a small corner porch located on the west side of Churchville Road about 1/4 mile north of Bodt Corner.

The gable roof has a center dormer with paired windows on the main elevation. An apparently modern reproduction balustrade encloses the small porch at the north corner. At the foot of the porch steps are turned newel posts of the type more often found on interior stairways. The main elevation has probably been altered with an enclosure of a wider porch. The present windows are aluminum. The exterior is clapboard and the foundation is rock-faced concrete. The roof is modern composition material.

Several frame and concrete block outbuildings are located just west of the house.

HA-1620

SPECIFIC DATES		BUILDER/ARCHITECT			
		_INVENTION			
<u>X</u> 1900-	COMMUNICATIONS	INDUSTRY	POLITICS/GOVERNMENT	_OTHER (SPECIFY)	
1800-1899	COMMERCE	EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION	
_1700-1799	ART	ENGINEERING	MUSIC	THEATER	
1600-1699	XARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN	
1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE	
1400-1499	ARCHEOLOGY-HISTORIC	CONSERVATION	LAW	SCIENCE	
REHISTORIC	ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	LANDSCAPE ARCHITECTURE	RELIGION	
`ERIOD	AREAS OF SIGNIFICANCE CHECK AND JUSTIFY BELOW				

STATEMENT OF SIGNIFICANCE

The White Frame Bungalow is a fair example of an early 20th century building form which became common in all parts of the U.S. Although altered, it retains the general outline of the bungalow form.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECE	SSARY
10 GEOGRAPHICAL DATA	
ACREAGE OF NOMINATED PROPERTY	
VERBAL BOUNDARY DESCRIPTION	
LICT ALL CTATES	
LIST ALL STATES AND COUNTIES FOR PROPERTIES	S OVERLAPPING STATE OR COUNTY BOUNDARIES
STATE	COUNTY
STATE	COUNTY
11 FORM PREPARED BY	
NAME / TITLE	
Janet Davis, MHT/SHA Survey	
ORGANIZATION	DATE
Md. Historical Trust	September 24, 1981
21 State Circle	(301) 269-2438
CITY OR TOWN	STATE
Annapolis	MD 21401
	· · · · · · · · · · · · · · · · · · ·

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.


The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust

The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438





HA-1620